## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


## IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


Colombia
















FIG.3a












FIG.6












FiG.11




FIG.13






FIG.I2










FIG.12a













FIG.20a FIG.20bFIG.20cFIG.20d














FIG.24




FIG.25




FIG.26




FIG.23a






FIG.24a





480 492 480 494 480 496

FIG.29a FIG.29b FIG.29c FIG.29d

FIG.30a FIG.30b FIG.30c FIG.30d





FIG.31






FIG.33





FIG.34






FIG.36

1)







FIG. 38










FIG.40




FIG.40a




FIG.41

**(\_)** 




FIG.44




FIG.47




FIG.46b


FIG.46c

1084

1082

1086

1074 1078 FIG.45






FIG.49







FIG.50

FIG.51










PRODUCT OUTLET HOLE TIP AFTER BEING BRO AWAY  $\nu^{1009}$ LEFT BEND FLAP UP TO SNAP TIP OFF THUMB HERE .2100 F16 550 2100 F16 559 F16.55e SEAL F16 55d F16.50


-




F16 56c









SEALED TIP IN CAP





Suff led






FIG. 100 63

FLOW CONTROL FOR FASY OPENING POUCH PARTICULARLY FOR VELOW VISCOSITY FLUIFE. SOY SAUCE, SKINHILK, WATER, ALCOH SOLVENTS ETC. ETC.

COMRISED OF ATLEA ONE SEAL TO BLOCK RATE OF PRODUCT FLOW FROM CONTAINMENT POCKET THE OUTLET HOLE,

